

**PRODUCT:** ACTpro

**MODEL/VERSION:** 3.2.0.84

**DATE:**

27-04-2022

The following changes have been made to ACTpro 3.2.0.84.

**Technical Changes for ACTpro 3.2.0.84:**

- An image of ACTpro-1500 firmware 1.11.10 has been added to the ACTpro software installation package.

**ACTpro-1500 firmware 1.11.10:**

- The ACTpro 1500 controller firmware has been updated to reduce delays on an Aperio Wireless lock from a maximum of 15 seconds to a maximum of 5 seconds between toggle/untoggled.
- The firmware will be shipped with ACTpro 3.2.0.82 or later. Additionally, the firmware can be obtained from our Technical Support Team.

**Related product:**

- V54502-C110-A100 ACTpro-1520 Door Controller, 2A 12V DC.
- V54502-C111-A100 ACTpro-1500 Door Controller.
- V54502-C112-A100 ACTpro-1500PoE Door Controller, PoE PSU.