



## Release Notes

Title: SMS Controller Firmware Release

Date: December 2023

Superseded Version: 7.16M / 7.59A

### OVERVIEW

Review the information contained herein for new features, enhancements and fixes included in the latest version of firmware for the VSRC-A, VRCNX-A, VSRC-M & VRCNX-M controllers designed to work with Vanderbilt SMS v7.3.0.

VSRC-A/VRCNX-A firmware v7.62A will work with SMS software versions prior to v7.3.0. However, Vanderbilt strongly recommends that SMS v7.3.0 be installed when utilizing VSRC-A based controller firmware v7.62A for the VRCNX-A and VSRC-A controllers.

VSRC-M/VRCNX-M firmware v7.20M will work with SMS software versions prior to v7.3.0. However, Vanderbilt strongly recommends that SMS v7.3.0 be installed when utilizing VSRC-M based controller firmware v7.20M for the VRCNX-M and VSRC-M controllers.

VSRC and VRCNX-R (legacy) controllers should be updated to firmware v6.70V.

SRCNX (legacy) controllers should be upgraded to firmware v6.58L.

While it is possible to utilize the SMS v7.3.0 software with lower firmware versions, not all new features will be available. Vanderbilt recommends that all controllers be updated to the latest firmware version available for each platform.

### ENHANCEMENTS

The following new features or enhancements are available:

#### VSCR-A & VRCNX-A

- Cybersecurity updates: OpenSSL, OpenSSH, LightTPD, SQLite, BusyBox and libxml2.
- Implement Linux Kernel patches to remediate CVE-2022-0215, CVE-2022-0286, CVE-2022-0850, CVE-2022-1016, CVE-2022-1184, CVE-2022-2663, CVE-2022-3566, CVE-2022-4304, CVE-2022-4378, CVE-2022-4450, CVE-2023-4622, CVE-2022-4662, CVE-2022-42703, CVE-2023-1095, CVE-2023\_2513, CVE-2023-2650, CVE-2023-3446, CVE-2023-32233, CVE-2023-36191, CVE-2023-38408, CVE-2023-39192, CVE-2023-39193, CVE-2023-42752.

acre security

ACRE Operating Group  
10181 Park Run Drive, Suite 190  
Las Vegas, Nevada, 89145  
USA

- Require use of DCT v2 for configuration changes and require authentication.  
*DCT v2 will be installed without removing any older version of the DCT which will still be required to manage controllers with older firmware.*

### **VSRC-M & VRCNX-M**

- Cybersecurity updates: OpenSSL, OpenSSH, LightTPD, SQLite, BusyBox and libxml2.
- Implement Linux Kernel patches to remediate CVE-2022-0215, CVE-2022-0286, CVE-2022-0850, CVE-2022-2663 & CVE-2022-4304, CVE-2022-4378, CVE-2022-4450, CVE-2023-2650, CVE-2023-3446, CVE-2023-36191, CVE-2023-38408, CVE-2023-39192, CVE-2023-39193.
- Require use of DCT v2 for configuration changes and require authentication.  
*DCT v2 will be installed without removing any older version of the DCT which will still be required to manage controllers with older firmware.*

### **FIXES**

The following issues have been resolved in this version:

#### **VSRC-A & VRCNX-A**

- DCT would not list controllers running firmware v7.59A under certain circumstances.
- Disable Web Login AutoComplete.

#### **VSRC-M & VRCNX-M**

- DCT would not list controllers running firmware v7.16M under certain circumstances.
- Disable Web Login AutoComplete.

### **VANDERBILT PRIVACY POLICY**

SMS does not transmit any data back to Vanderbilt. Any personal data collected within SMS is managed and used exclusively by the end-user of SMS entirely on customer owned equipment. Vanderbilt does not collect, manage or sell personal data. Please visit the Vanderbilt website at <https://usa.vanderbiltindustries.com/legal> for more information on our privacy policy.